

ID No. 00478	<b>Product/Process Change Notification</b>	Date 18 April 2018
<b>Product</b> PLS8-X	<b>Ordering Code</b> L30960-N3460-A300	
Ordering No. changes:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
New Ordering Code:	<b>L30960-N3460-B300</b>	

**Reason of Change:**

- |  |  |
|--|--|
| <input type="checkbox"/> Technical requirement           | <input type="checkbox"/> Change of production process/logistical changes |
| <input checked="" type="checkbox"/> Customer requirement | <input type="checkbox"/> Location of production moved                    |
| <input type="checkbox"/> Quality improvement             | <input type="checkbox"/> Other: 2 <sup>nd</sup> source material          |

<b>Description of change:</b>	<p>A configuration change was made to enable newer cryptographic methods such as SHA256. Further, the update routine for OTA DM certificates was improved.</p> <p>This updated configuration will be manufactured from May 2018 onwards.</p> <p>These changes concern application level components only and do not affect the protocol stack.</p> <p>The final, validated update firmware image can be made available via your technical sales representative</p>
<b>Scheduled date of introduction (cw/year):</b>	CW18/2017
<b>Timing note:</b>	If Gemalto M2M GmbH does not receive a notification to the contrary within a period of 6 weeks, Gemalto M2M GmbH assumes that the customer agrees to the change.

<b>Quality assurance measurements:</b>	The new version fulfils all internal test requirements according to our Quality Management process and philosophy.
--	--

19.04.2018

19.04.2018

X 

Frank Ryll  
Product Manager  
Signiert von: Frank Ryll 10015116

X 

Jörg Erdmann  
Vice President Quality Management  
Signed by: Joerg Erdmann 10015214

**Attachments:**

-